EXECUTIVE SUMMARY

Introduction

- 1. This is the 11th Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the "Agreement No. EDO 5/2019 Environmental Team for Kai Tak Development" (hereinafter called "the Project"). This report documents the findings of EM&A Works conducted in April 2021.
- 2. During the reporting month, the following works contracts were undertaken within Kai Tak Site:
 - KL/2012/03 Kai Tak Development Stage 4 Infrastructure at Former North Apron Area
 - KL/2014/01 Kai Tak Development Stage 2 Infrastructure Works for Developments at the Southern Part of the Former Runway
 - KL/2014/03 Kai Tak Development Stage 3 Infrastructure Works for Developments at the Southern Part of the Former Runway
 - KL/2015/02 Kai Tak Development Stage 5A Infrastructure at Former North Apron Area
 - KL/2015/03 Kai Tak Development Stage 3B Infrastructure at Former North Apron Area
 - 6/WSD/08 & 7/WSD/08 Replacement and Rehabilitation of Water Mains Stages 2 & 3
 - SS G506 Construction of Station Square at Kai Tak Phase I
 - 1389EM18A District Cooling System (DCS) at Kai Tak Development (KTD) Chilled Water Pipe Laying and Associated Works in North Apron
 - 2852EM17A District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package D) – Water Pipe Laying Works
 - 2853EM17W District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package D) Electrical and Mechanical Installation
 - HY/2014/18 Provision of Barrier-Free Access Facilities for Highway Structure Phase 3 Contract 7
 - HY/2014/07 Central Kowloon Route Kai Tak West
 - SCL1109 MTR Shatin to Central Link: Ma Tau Wai and To Kwa Wan Stations and Tunnels
 - SCL1121 MTR Shatin to Central Link: Cross Harbour Tunnels
 - SCL1123 MTR Shatin to Central Link: Exhibition Station and Western Approach Tunnel
 - New Kowloon Inland Lot No. 6556 Residential Development at Kai Tak Area 1F Site 2
 - New Kowloon Inland Lot No. 6557 Commercial Development at Kai Tak Area 1E Site 2
 - New Kowloon Inland Lot No. 6562 Residential Development at Kai Tak Area 1K Site 3
 - New Kowloon Inland Lot No. 6563 Residential Development at Kai Tak Area 1L Site 1
 - New Kowloon Inland Lot No. 6564 Residential Development at Kai Tak Area 1L Site 2
 - New Kowloon Inland Lot No. 6565 Residential Development at Kai Tak Area 1L Site 3
 - New Kowloon Inland Lot No. 6566 Residential Development at Kai Tak Area 1K Site 2
 - New Kowloon Inland Lot No. 6567 Residential Development at Kai Tak Area 1K Site 1
 - New Kowloon Inland Lot No. 6568 Residential Development at Kai Tak Area 1F Site 1
 - New Acute Hospital at Kai Tak Development Area foundation, excavation and lateral support, and basement excavation works Site A 8110059224
 - New Acute Hospital at Kai Tak Development Area foundation, excavation and lateral support, and basement excavation works Site B 8110059225
 - HAB/KTSP/01 Design, Construction and Operation of the Kai Tak Sports Park at Kai Tak, Kowloon City District, Hong Kong

Environmental Monitoring Works

- 3. Environmental monitoring for the Project was performed in accordance with the EM&A Manual and the monitoring results were checked and reviewed. Site Inspections/Audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 4. Summary of the non-compliance in the reporting month for the Project is tabulated in Table I.

Parameter	No. of Exceedance		Action
	Action Level	Limit Level	Taken
1-hr TSP	0	0	N/A
24-hr TSP	0	0	N/A
Noise	0	0	N/A

 Table I
 Non-compliance Record for the Project in the Reporting Month

1-hour & 24-hour TSP Monitoring

- 5. All 1-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 6. All other 24-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 7. The air quality monitoring results in the reporting month are presented in Table II.

I able II	Air Quanty Monitoring Results in the Reporting Month		
Monitoring Station	Description	1-hour TSP (μg/m ³)	24-hour TSP (μg/m ³)
AM1(C)	Contractor's Site Office of KL/2015/03	22 - 82	85.5 - 143.9
AM2	Lee Kau Yan Memorial School	36 - 80	31.8 - 87.6
AM3(A)	Holy Trinity Bradbury Centre	35 - 128	48.6 - 102.9
AM4(D)	The Factory for the Blind	35 - 74	47.2 - 83.9
AM5(B)	CCC Kei To Secondary School	20 - 110	26.1 - 55.8
AA1	Ching Long Shopping Centre	26 - 74	46.1 - 85.5

 Table II
 Air Quality Monitoring Results in the Reporting Month

AA2	Tak Long Estate	22 - 63	15.1 – 43.6
AA4	Hong Kong Children's Hospital	21 - 34	56.8 - 129.7

Construction Noise

- 8. All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded
- 9. The noise monitoring results in the reporting month are presented in Table III.

Monitoring Station	Description	Noise Level, Leq (30mim) dB(A)	
M1	Buddhist Chi King Primary School	58.5 - 63.2	
M2	S.K.H. Kowloon Bay Kei Lok Primary School	64.9 – 67.1	
M3	Rhythm Garden	66.1 – 76.1	
M4(A)	The Bridge connecting the Latitude	72.2 - 74.2	
M5	Lee Kau Yan Memorial School	72.8 - 74.9	
M6(C)	Mercy Grace's Home	69.6 – 75.3	
M7(A)	Oblate Primary School	58.6 - 62.7	
M8	CCC Kei To Secondary School	58.0 - 61.3	
M9	Near Chi Yun School	51.7 - 61.2	
M10	Tak Long Estate Car Park	43.6 - 59.9	
MA1	Ching Long Shopping Centre	62.8 - 65.1	
MA3	Hong Kong Children's Hospital	66.1 – 70.9	

Table III Noise Monitoring Results in the Reporting Month

Key Information in the Reporting Month

10. Summary of key information in the reporting month is tabulated in Table IV.

Event	Event Details		Action Taken	Status	Remark
	Number	Nature			
Complaint received	9	Noise, wastewater	Details are shown in Appendix L	30 complaints are under investigation	
Reporting Changes	0		N/A	N/A	
Notifications of any summons & prosecutions received	0		N/A	N/A	

 Table IV
 Summary Table for Key Information in the Reporting Month

Future Key Issues

11. The future key environmental issues in the coming month include:

- Dust generation from stockpiles of dusty materials, exposed site area, excavation works and rock breaking activities;
- Watering for dust generating activity and on haul road;
- Proper storage of construction materials on site;
- Storage of chemicals/fuel and chemical waste/waste oil on site;
- Accumulation of general and construction waste on site;
- Noise from operation of the equipment, especially for rock-breaking activities, piling works and machinery on-site;
- Runoff from exposed slope;
- Wastewater and runoff discharge from site;
- Regular removal of silt, mud and sand along u-channels and sedimentation tanks; and
- Review and implementation of temporary drainage system for the surface runoff.

EM&A REPORT FOR APRIL 2021 (FULL VERSION)

PDF/HTML