EXECUTIVE SUMMARY

Introduction

- 1. This is the 13th Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the "Agreement No. EDO 5/2019 Environmental Team for Kai Tak Development" (hereinafter called "the Project"). This report documents the findings of EM&A Works conducted in June 2021.
- 2. During the reporting month, the following works contracts were undertaken within Kai Tak Site:
 - KL/2012/03 Kai Tak Development Stage 4 Infrastructure at Former North Apron Area
 - KL/2014/01 Kai Tak Development Stage 2 Infrastructure Works for Developments at the Southern Part of the Former Runway
 - KL/2014/03 Kai Tak Development Stage 3 Infrastructure Works for Developments at the Southern Part of the Former Runway
 - KL/2015/02 Kai Tak Development Stage 5A Infrastructure at Former North Apron Area
 - KL/2015/03 Kai Tak Development Stage 3B Infrastructure at Former North Apron Area
 - 6/WSD/08 & 7/WSD/08 Replacement and Rehabilitation of Water Mains Stages 2 & 3
 - SS G506 Construction of Station Square at Kai Tak Phase I
 - 1389EM18A District Cooling System (DCS) at Kai Tak Development (KTD) Chilled Water Pipe Laying and Associated Works in North Apron
 - 2852EM17A District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package D) – Water Pipe Laying Works
 - 2853EM17W District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package D) Electrical and Mechanical Installation
 - HY/2014/18 Provision of Barrier-Free Access Facilities for Highway Structure Phase 3 Contract 7
 - HY/2014/07 Central Kowloon Route Kai Tak West
 - SCL1109 MTR Shatin to Central Link: Ma Tau Wai and To Kwa Wan Stations and Tunnels
 - SCL1121 MTR Shatin to Central Link: Cross Harbour Tunnels
 - SCL1123 MTR Shatin to Central Link: Exhibition Station and Western Approach Tunnel
 - New Kowloon Inland Lot No. 6556 Residential Development at Kai Tak Area 1F Site 2
 - New Kowloon Inland Lot No. 6557 Commercial Development at Kai Tak Area 1E Site 2
 - New Kowloon Inland Lot No. 6562 Residential Development at Kai Tak Area 1K Site 3
 - New Kowloon Inland Lot No. 6563 Residential Development at Kai Tak Area 1L Site 1
 - New Kowloon Inland Lot No. 6564 Residential Development at Kai Tak Area 1L Site 2
 - New Kowloon Inland Lot No. 6565 Residential Development at Kai Tak Area 1L Site 3
 - New Kowloon Inland Lot No. 6566 Residential Development at Kai Tak Area 1K Site 2
 - New Kowloon Inland Lot No. 6567 Residential Development at Kai Tak Area 1K Site 1
 - New Kowloon Inland Lot No. 6568 Residential Development at Kai Tak Area 1F Site 1
 - New Acute Hospital at Kai Tak Development Area foundation, excavation and lateral support, and basement excavation works Site A-8110059224
 - New Acute Hospital at Kai Tak Development Area foundation, excavation and lateral support, and basement excavation works Site B-8110059225
 - HAB/KTSP/01 Design, Construction and Operation of the Kai Tak Sports Park at Kai Tak, Kowloon City District, Hong Kong

Environmental Monitoring Works

- 3. Environmental monitoring for the Project was performed in accordance with the EM&A Manual and the monitoring results were checked and reviewed. Site Inspections/Audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 4. Summary of the non-compliance in the reporting month for the Project is tabulated in **Table I**.

Table I Non-compliance Record for the Project in the Reporting Month

Parameter	No. of E	No. of Exceedance	
	Action Level	Limit Level	Taken
1-hr TSP	0	0	N/A
24-hr TSP	0	0	N/A
Noise	0	0	N/A

1-hour & 24-hour TSP Monitoring

- 5. All 1-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 6. All other 24-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 7. The air quality monitoring results in the reporting month are presented in **Table II**.

Table II Air Quality Monitoring Results in the Reporting Month

Monitoring Station	Description	1-hour TSP (μg/m³)	24-hour TSP (μg/m³)	
AM1(C)	Contractor's Site Office of KL/2015/03 30.0 – 65.0		52.1 - 86.4	
AM2	Lee Kau Yan Memorial School	14.7 – 55.0	28.6 – 133.0	
AM3(A)	Holy Trinity Bradbury Centre	12.5 – 75.0	26.9 - 41.1	
AM4(D)	The Factory for the Blind	17.5 – 80.5	20.7 - 68.1	
AM5(B)	CCC Kei To Secondary School	30.0 – 70.0	15.4 - 37.5	
AA1	Ching Long Shopping Centre	32.2 – 70.2	24.2 - 46.5	
AA2	Tak Long Estate	26.0 – 72.8	11.8 - 23.3	
AA4	Hong Kong Children's Hospital	23.1 – 80.5	23.9 - 60.5	

Construction Noise

- 8. All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded
- 9. The noise monitoring results in the reporting month are presented in **Table III**.

Table III Noise Monitoring Results in the Reporting Month

Monitoring Station	Description	Noise Level, Leq(30 min) dB(A)		
M1	Buddhist Chi King Primary School	60.2 - 63.2		
M2	S.K.H. Kowloon Bay Kei Lok Primary School	52.2 - 67.6		
M3	Rhythm Garden	74.3 – 76.2		
M4(A)	The Bridge connecting the Latitude	71.6 – 75.2		
M5	Lee Kau Yan Memorial School	65.3 – 75.8		
M6(C)	Mercy Grace's Home	63.9 – 75.3		
M7(A)	Oblate Primary School	57.1 – 61.4		
M8	CCC Kei To Secondary School	57.3 – 62.3		
M9	Near Chi Yun School	55.4 – 65.4		
M10	Tak Long Estate Car Park	50.8 – 64.6		
MA1	Ching Long Shopping Centre	52.6 – 65.4		
MA3	Hong Kong Children's Hospital	61.7 – 71.3		

Key Information in the Reporting Month

10. Summary of key information in the reporting month is tabulated in **Table IV**.

Table IV Summary Table for Key Information in the Reporting Month

Event	Event Details		Action Taken	Status	Remark	
Event	Number	Nature	Action Taken	Status	Remark	
Complaint received	7	Air, noise & water	Details are shown in Appendix L	8 complaints are under investigation		
Reporting Changes	0		N/A	N/A		
Notifications of any summons & prosecutions received	0		N/A	N/A		

Future Key Issues

- 11. The future key environmental issues in the coming month include:
 - Dust generation from stockpiles of dusty materials, exposed site area, excavation works and rock breaking activities;
 - Watering for dust generating activity and on haul road;
 - Proper storage of construction materials on site;
 - Storage of chemicals/fuel and chemical waste/waste oil on site;
 - Accumulation of general and construction waste on site;
 - Noise from operation of the equipment, especially for rock-breaking activities, piling works and machinery on-site;
 - Runoff from exposed slope;
 - Wastewater and runoff discharge from site;
 - Regular removal of silt, mud and sand along u-channels and sedimentation tanks; and
 - Review and implementation of temporary drainage system for the surface runoff.

THE FULL VERSION EM&A REPORT FOR JUNE 2021 CAN BE VIEWED FROM THE ARCHIVED REPORT