### **EXECUTIVE SUMMARY**

### Introduction

- 1. This is the 13<sup>th</sup> Environmental Monitoring and Audit (EM&A) Report prepared by Castco Testing Center Limited (CTCL) "Contract No. KLN/2016/09 Environmental Monitoring Works for Kai Tak Development" (hereinafter called "the Project"). This report documents the findings of EM&A Works conducted in March 2018.
- 2. During the reporting month, the following works contracts were undertaken within Kai Tak Site:
  - 1020EM12A District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package A) – Chilled Water Pipe Laying Works
  - 2477EM14A –District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package B)-Water Pipe Laying Works
  - 2487EM14W District Cooling System (DCS) at Kai Tak Development (KTD) Phase III (Package B)-Electrical and Mechanical Installation
  - 1107 MTR Shatin to Central Link: Diamond Hill to Kai Tak Tunnels
  - 1108 MTR Shatin to Central Link: Kai Tak Station and Associated Tunnels
  - 1109 MTR Shatin to Central Link: Ma Tau Wai and To Kwa Wan Stations and Tunnels
  - 1123 MTR Shatin to Central Link: Exhibition Station and Western Approach Tunnel
  - 1114 MTR Shatin to Central Link: Pedestrian Links at Tsz Wan Shan
  - 20150362 Construction of Home Ownership Scheme at Kai Tak Site 1G1(B)
  - 3/WSD/08, 6/WSD/08, 7/WSD/08, 8/WSD/08 Replacement and Rehabilitation of Water Mains Stages 2 & 3
  - KL/2011/01 Kai Tak Development Reconstruction and Upgrading of Kai Tak Nullah
  - KL/2012/02 Kai Tak Development Stage 3A Infrastructure at Former North Apron Area
  - KL/2012/03 Kai Tak Development Stage 4 Infrastructure at Former North Apron Area
  - KL/2014/01 Kai Tak Development Stage 2 Infrastructure Works for Developments at the Southern Part of the Former Runway
  - KL/2014/03 Kai Tak Development Stage 3 Infrastructure Works for Developments at the Southern Part of the Former Runway
  - KL/2015/02 Kai Tak Development Stage 5A Infrastructure at Former North Apron Area
  - KL/2015/03 Kai Tak Development Stage 3B Infrastructure at former North Apron Area
  - New Kowloon Inland Lot No. 6525 Residential Development at Kai Tak Area 11 Site 1
  - New Kowloon Inland Lot No. 6526 Residential Development at Kai Tak Area 11 Site 2
  - New Kowloon Inland Lot No. 6527 Residential Development at Kai Tak Area 11 Site 3
  - New Kowloon Inland Lot No. 6541 Residential Development at Kai Tak Area 1H Site 3
  - New Kowloon Inland Lot No. 6562, 6563, 6564 &6565 Residential Development Residential Development at Kai Tak Area 1K Site1, Site 2, Site 3 and 1L Site 1, Site 2, Site 3
  - New Kowloon Inland Lot No. 6566 Residential Development at Kai Tak Area 1K Site 2
  - New Kowloon Inland Lot No. 6567 Residential Development at Kai Tak Area 1K Site 1

- New Kowloon Inland Lot No. 6557 Commercial Development at Kai Tak Area 1E Site 2
- SS A501 Design and Construction of Centre of Excellence in Paediatrics
- SS E517 Construction site of 30-classroom secondary school at Site 1A-2, Kai Tak
- SS C503 Design and Construction of Kowloon East Regional Headquarters and Operational Base cum Ngan Tau Kok Divisional Police Station at 105 Concorde Road, Kai Tak
- SD E516 Demolition of Existing Structures of Sung Wong Toi Vehicle Repair and Maintenance Workshop
- HY/2014/18 Provision of Barrier-Free Access Facilities for Highway Structures Phase 3 Contract 7
- 3. Stockpiling of excavated & construction materials, storage of equipment, business in the recovery and recycling and car parks, etc. are the major activities for short term tenancy (STT) / temporary government land allocation (TGLA).

#### Environmental Monitoring Works

- 4. Environmental monitoring for the Project was performed in accordance with the EM&A Manual and the monitoring results were checked and reviewed. Site Inspections/Audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 5. Summary of the non-compliance in the reporting month for the Project is tabulated in Table I.

# Table I Non-compliance Record for the Project in the Reporting Month

Denemeter	No. of Ex	Action Taken	
Parameter	Action Level	Limit Level	ACTION LAKEN
1-hr TSP	0	0	N/A
24-hr TSP	0	0	N/A
Noise	0	0	N/A

1- hour & 24-hour TSP Monitoring

- 6. All 1-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 7. All 24-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 8. The air quality monitoring results in March 2018 are presented in Figure.1.

Table 2 Air Quanty Monitoring Results in March 2018 Monitoring Station			
Monitoring	Description	<b>1-hour TSP</b>	24-hourTSP
Station I		(μg/ m <sup>3</sup> )	(µg/m³)

# Table 2 Air Quality Monitoring Results in March 2018 Monitoring Station

Agreement No. EDO/02/2017 Administration of Environmental Team and Independent Environmental Checker for Kai Tak Development (2017-2022)

AM1(C)	Contractor's Site Office of KL/2015/03	114 - 201	94 - 155
AM2	Lee Kau Yan Memorial School	77 - 160	61 - 103
M3(A)	Holy Trinity Bradbury Centre	58 - 132	45 - 124
AM4(C)	NFS Pump Room	134 - 201	129 - 182
AM5(B)	CCC Kei To Secondary School	77 - 111	70 - 105
AA1	Ching Long Shopping Centre	56 - 131	38 - 108
AA2	Tak Long Estate	90 - 141	79 - 121

### **Construction** Noise

- 9. All construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded.
- 10. The noise monitoring results in March 2018 are presented in Figure.2.

Monitoring Station	Description	Allowable Noise Level Leq (30min) dB (A)	Noise Level Leq (30min) dB (A)
M1	Buddhist Chi King Primary School	70	60 - 64
M2	SKH Kowloon Bay Kei Lok Primary School	70	53 - 59
M3	Rhythm Garden	76.3	75 - 76
M4	Cognitio College	80	66 - 78
M5	Lee Kau Yan Memorial School	76.7	63 - 75
M6(C)	Mercy Grace's Home	78	66 - 78
M7(A)	Oblate Primary School	70	48 - 65
M8	CCC Kei To Secondary School	70	61 - 68
M9	Po Leung Kuk Ngan Po Ling College	70	58 - 63
M10	Tak Long Estate	75	55 - 62

MA1 Ching Long Shopping Centre	75	66 - 70
-----------------------------------	----	---------

Key Information in the Reporting Month

11. Summary of key information in the reporting month is tabulated in Table II.

#### Table IISummary Table for Key Information in the Reporting Month

Event	Event Details		Action taken	Status	Remark
	Number	Nature	Action taken	Status	Keillark
Complaint received	1	Construction Noise	Investigation conducted by Contractor	Closed	
Reporting Changes	0		N/A	N/A	
Notifications of any summons & Prosecutions received	0		N/A	N/A	

#### Future Key Issues

- 12. The future key environmental issues in the coming month include:
  - Dust generation from stockpiles of dusty materials, exposed site area, excavation works and rock breaking activities;
  - Watering for dust generating activity and on haul road; Proper storage of construction materials on site;
  - Storage of chemicals/fuel and chemical waste/waste oil on site;
  - Accumulation of general and construction waste on site;
  - Noise from operation of the equipment, especially for rock-breaking activities, piling works and machinery on-site;
  - Runoff from exposed slope;
  - Wastewater and runoff discharge from site;
  - Regular removal of silt, mud and sand along u-channels and sedimentation tanks; and
  - Review and implementation of temporary drainage system for the surface runoff.

#### EM&A REPORT FOR MARCH 2018 (FULL VERSION)

# <u>PDF / HTML</u>